

THERMOMETER & HYGROMETER

MODEL: GWS-2001K



I. DIMENSIONS: 72*34.2*16.1MM

II. SPECIFICATION:

Temperature measuring function:

1. **RANGE: 0.0°C to 70.0°C (32°F to 158°F)**
2. **RESOLUTION: 0.1°C (or 0.2°F) IN ROOM TEMP.**
3. **ACCURACY: +/-1°C / +/-2°F**
4. **MAX. AND MIN RECALL FUNCTION.**
5. **CLEAR KEY TO DELETE MAX. MIN RECORD**
6. **POWER ON/ OFF KEY**

Humidity measuring function:

1. **RANGE: 20% TO 90% (BETWEEN 0°C~60°C)**
2. **RESOLUTION: 1%**
3. **ACCURACY : + / - 5%(25°C)**
4. **MAX. AND MIN RECALL FUNCTION.**
5. **CLEAR KEY TO DELETE MAX. MIN RECORD**
6. **POWER ON/ OFF KEY**

SAMPLING RATE : 10 SECS. OR 1 MINUTE.

POWER SUPPLY: CR2032 3V

C/F SELECTION ON PCB

勝特力材料 886-3-5753170
勝特力电子(上海) 86-21-54151736
勝特力电子(深圳) 86-755-83298787

[Http://www.100y.com.tw](http://www.100y.com.tw)

勝特力材料 886-3-5753170
勝特力电子(上海) 86-21-54151736
勝特力电子(深圳) 86-755-83298787

[Http://www.100y.com.tw](http://www.100y.com.tw)