

英美制蝶形螺母

Socket head bolts

Due to the differences in chemical composition and make them both the corrosion resistance of different, ordinary stainless steel is generally not resistant to chemical corrosion medium, and acid is commonly have stainless steel.



碳钢蝶形螺母

优质碳钢材料，表面镀白锌，起到一定的防锈作用，表面光滑，无毛刺。

Chromium and nickel elements combined effect generated in the material surface layer of the oxidation resistance, abrasion resistance



1.

优质钢材

Standard cross groove, the installation process is not easy to appear pits
& phenomenon, greatly saves installation time

标准碳钢材料，表面处理，防生锈，按标准生产，
尺寸标准，做工好。

Screw the groove depth, specifications are standard surface smooth.
Standard steel material, can put the company



螺旋螺纹


2.

Standard cross groove, the installation process is not easy to appear pits
& phenomenon, greatly saves installation time

优质材料配合加工工艺，螺纹清晰，不易滑牙，
耐滑耐磨。

Screw section is smooth level off, without burr, residual rotation
The process is not easy to exist





把1英寸分成16等分，那么一段的长度就是1/16，二段的长度就是2/16，简化后为1/8，以此类推！七段的长度就是7/16，八段就是16/8.....

把1英寸分成64等分，那么一段的长度就是1/64，二段的长度就是2/64，简化后为1/32，以此类推！七段的长度就是7/16，八段就是16/8.....

公英制换算

1英寸=25.4mm
 1/8英寸=25.4*1/8=3.175mm
 1/2英寸=25.4*1/2=12.7mm
 以此类推.....

英制牙距换算

1/4-20:表示螺纹直径1/4英寸，20表示螺距，意思是1英寸长的距离有20圈螺纹，换成公制，牙距为25.4mm/20=1.27mm

3/8-16:表示螺纹直径3/8英寸，16表示螺距，意思是1英寸长的距离有16圈螺纹，换成公制，牙距为25.4mm/16=1.5875mm，以此类推....

公制英制螺纹牙距表

公制	牙距			英制 美制	称呼	牙数		
	粗牙	细牙	极细牙			粗牙	细牙	韦氏牙
M3	0.5	0.35		4#	1.9	40	48	
M4	0.7	0.5		6#	3.5	32	40	
M5	0.8	0.5		8#	4.2	32	36	
M6	1.0	0.75		10#	4.8	24	32	
M7	1	0.75		12#	5.5	24	28	
M8	1.25	1.0	0.75	1/4	6.35	20	28	20
M10	1.5	1.25	1.0	5/16	7.94	18	24	18
M12	1.75	1.5	1.25	3/8	9.53	16	24	16
M14	2.0	1.5	1.0	7/16	11.11	14	20	14
M16	2.0	1.5	1.0	1/2	12.7	13	20	12
M18	2.5	2.0	1.5	9/16	14.29	12	18	12
M20	2.5	2.0	1.5	5/8	15.86	11	18	11
M22	2.5	2.0	1.5	3/4	19.05	10	16	10
M24	3.0	2.0	1.5	7/8	22.23	9	14	9
M27	3.0	2.0	1.5	1	25.4	8	12	8
M30	3.5	3.0	2.0					