

TM-28E AC/DC True RMS Watt Meter is designed and built for use in an environment of pollution degree 2 according to IEC 1010-1 CAT II 1000V, IEC 1010-1 CAT III 600V and IEC 1010-2-032 CAT III 600V.

勝特力材料 886-3-5753170
勝特力电子(上海) 86-21-54151736
勝特力电子(深圳) 86-755-83298787
[Http://www.100y.com.tw](http://www.100y.com.tw)

◇ DISPLAY

- Back light 3 3/4 digits LCD with max. reading 3999, plus decimal point, unit symbol indication.
- Overload Indication: LCD will show “OL” in the upper left position.
- Low Battery Indication: Replace battery immediately when LCD displays “ ”.

◇ FUNCTIONS

- Conversion type: Trms
- Auto Range, Auto Power Off, Auto Zero
- High speed bargraph
- Function Keys: Max/Min Hold, Data Hold, Trms Positive and Negative Peak Hold
- Test Ranges: ACV, ACA, DCV, DCA, Ω, WATT, Frequency, Continuity
- The maximum conductor size is 35mm.

◇ SAMPLING SPEED

- Sampling Rate: 2 times per second for digital display.

◇ ACCESSORIES

- Instruction manual
- Carrying case
- 9V Battery x 1pc
- Test leads

◇ POWER SUPPLY

- Battery type : 9V NEDA 1604 IEC 6F22 JIS 006P battery x 1pc
- Battery life : 200 hours approx.

◇ OPERATION CONDITION

- Operating Temperature & Humidity: 5℃ ~ 40℃, below 80%RH.
- Storage Temperature & Humidity: -10℃ ~ 60℃, below 70%RH.

◇ DIMENSION

- Size : 218 x75x43mm(LxWxH)
- Weight: about 375 g (including battery)

