

TPM-10 说明书

特点

数字温度显示，嵌入式设计，外观简洁，两节纽扣电池供电，使用时间更长久，尤其适用于冰箱、冷柜、展示柜等。

技术参数

- 测温范围：-50℃ ~ +70℃
- 使用环境：-10℃ ~ +50℃
- 电源：两节纽扣电池(AG13,1.5V)
- 精度：±1℃
- 分辨率：0.1℃

使用说明

- 打开电池盖，放入两节AG13纽扣电池，注意正负极，不要放反。
- 电池装入即显示。长期不使用，请取出电池。（注：首次使用时，请拉出绝缘片）
- 温度高于70℃时，LCD显示H℃
温度低于-50℃时，LCD显示L℃
- 嵌入尺寸：46mm × 26.6mm

Operating Instruction (TPM-10F)

Features

- LCD display.
- Insert design.
- Simple appearance.
- Two button batteries for longer use time.
- Especially applied in refrigerator, chiller, deepfreeze etc.

Technical parameter

- Temperature range: $-50^{\circ}\text{C} \sim +80^{\circ}\text{C}$
- Using environment: Temperature: $-5^{\circ}\text{C} \sim +50^{\circ}\text{C}$
Humidity: $5\% \sim 80\%$
- Accuracy: $\pm 1^{\circ}\text{C}$ ($-20^{\circ}\text{C} \sim +40^{\circ}\text{C}$)
- Resolution: 1 ($\leq -20^{\circ}\text{C}$) 0.1 ($> -20^{\circ}\text{C}$)
- Power: two button battery (LR44, 1.5v)

Instruction

- Open the battery cover to put in two LR44 batteries correctly, pay attention to the polarity.
- Display when put in the batteries. Pls take out the batteries when not use for long time
- LCD display “--.°C” when temperature is lower than -50°C .
- Insert size: 46 x 26.6mm